



BRASS Stock NEEDS to be at least $\frac{1}{8}$ " thick AND $\frac{3}{4}$ " WIDE. Cut to REQD length AND DRILL holes for clamping SCREWS AND fixture pipe.

Bob Dey
3/3/16